'N THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Fant et al.

Attorney Docket No.: CALIP005/P050

Patent No.: 6,950,215 B2

Issued: September 27, 2005

Title: METHOD AND APPARATUS FOR MONITORING OPTICAL SWITCHES

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the U.S. Postal Service with sufficient postage as first-class mail on February 2, 2006 in an envelope andressed to the Commissioner for Patents, P.O. Box 1450 Alexandria, VA 223/13-1450.

REQUEST FOR CERTIFICATE OF CORRECTION OF APPLICANT'S MISTAKE (35 U.S.C §255, 37 C.F.R. §1.323)

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Attn: Certificate of Correction Certificate

FEB 1 3 2006

of Correction

Dear Sir:

Attached is Form PTO-1050 (Certificate of Correction) at least one copy of which is suitable for printing.

A mistake of a clerical or typographical nature, or minor in character appears in the above-referenced patent; however, the mistake occurred in good faith. The correction introduces no new matter nor requires reexamination. The mistake occurred because it was inadvertently cut off before filing.

The errors together with the exact page and line number where the errors appear in the application file are as follows:

SPECIFICATIONS:

Column 2, line 6, add --active optical switch 108, the active optical switch may be 1. removed from service by-- after "detected in the." This error appears in the patent application as filed on July 11, 2001, and was cut off page 2.

Check No. 29186 in the amount of \$100.00 is enclosed in accordance with 37 CFR § 1.20(a). However, if it is determined that any fees are due, the Commissioner is hereby authorized to charge such fees to Deposit Account 500388 (Order No. CALIP005).

Respectfully submitted,

BEYER WEAVER & THOMAS, LLP

Michael Lee

Registration No. 31,846

P.O. Box 70250 Oakland, CA 94612-0250 650-961-8300 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control number

(Also Form PT-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,950,215 B2

DATED : September 27, 2005

INVENTOR(S): Fant et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In the Specifications:

Column 2, line 6, add --active optical switch 108, the active optical switch may be removed from service by-- after "detected in the."

MAILING ADDRESS OF SENDER:

PATENT NO. 6,950,215 B2

No. of Additional Copies

Michael Lee BEYER WEAVER & THOMAS, LLP P.O. Box 70250 Oakland, CA 94612-0250

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

FEB 13 2006